32 13 11

CONCRETE PAVEMENT FOR AIRFIELDS AND OTHER HEAVY-DUTY PAVEMENTS

PUNCHLIST / WALK 2/10/16

General Notes

1. Test Reports uploaded to submittal exchange

(Need to be officially submitted per paragraph 1.2.4) Straightedge Test revealed 1 deficient area ¼" out of tolerance)

- 2. Striping (Environmental Conditions) Separate DFOW
- 3. Joint Sealants (Environmental Conditions) Separate DFOW
- 4. Asphalt overage on HD Paving edge or Broken concrete-See pictures
- 5. Surface irregularities-See pictures
- 6. Concrete slag in spots-remove
- 7. Grade at North East end and South West end of taxiway needs rework in green space.

Please note that coordination between PMO/NAVFAC/AirOpps/Carothers must take place in order to correct items 2-7.









P.O. Box 189 Taylor, MS 38673 Phone: (662) 513-8820

Fax: (662) 234-3292



P465 AIRCRAFT HANGAR WALK THROUGH PHASE I CAROTHERS/NAVFAC SIGN-IN SHEET

DATE: 2/10/2016

Name:	Organization/Company Name:	Phone Number:	Email:	
b) (6)	Carothers Construction NAVFAC			